

O.N. 54/25-7-26

HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT

NO-PW-KMS-WA-Building /2026-

2990-97

Dated:-

23/11/16

To

✓ The Principal ,
D.A.V.Sr.Sec. Public.School.
Kumarsain, Tehsil Kumarsain,
Distt. Shimla (HP).

Subject:-

Request for the issue of Building safety certificate .

Reference: -

Your letter No. 5867 dated 20-07-2025.

In this connection it is intimated that the building safety certificate of D.A.V.Sr.Sec.Public.School building at Kumarsain, Distt. Shimla HP as received from the Assistant Engineer Kumarsain Sub-Division HPPWD Kumarsain vide his letter No. PW-KSD-Building/2026-489 dated 02-07-2026 for the year 2026-27 is sent herewith for taking further necessary action.

Encl:- As above.


Executive Engineer,
Kumarsain Division,
HPPWD, Kumarsain.

Copy to Assistant Engineer, Kumarsain Sub-Division HPPWD
Kumarsain for information with reference to above.

✓
Executive Engineer,
Kumarsain Division,
HPPWD, Kumarsain.

BUILDING SAFETY CERTIFICATE

No.

Date: 21/07/2026

It is certified that the existing building D.A.V. Public School Kumarsain (name of the building premises) at Lathi, Kumarsain, distt. Shimla H.P. (address) is having block(s) /Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor(s) in the block	5 (nos)					

The building is owned/occupied by D.A.V. Public School Kumarsain (name of the institution) have complied with the building safety requirement in accordance with National Building code Rules, and verified by the officers concerned of HP.PWD (Name of Department Govt.) on 21/07/2026 (date of inspection) in the presence of Sh. Ramesh Sharma, Principal, DAV Public School 14/sain (name and addresses of the Manager/ Secretary or his representative) and that the building/ premises is fit for occupancy for running school with effect from 21/7/26 for a period of one years in accordance with rule and subject to compliance of the specific condition as appended.

1. The building has been constructed by DAV Management
2. during 2005 and is a Rcc frame structure and cannot be
3. verified structurally but appears safe visually.
4. The structural stability cannot be issued because this building is not constructed by HP.PWD.

Issued on 21-7-26 at Kumarsain by Ex-En. PWD.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Assistant Engineer
Kumarsain Sub-Division
HPWD Kumarsain

Signature with seal:

Executive Engineer
Kumarsain Division
HP.PWD Kumarsain

Name: Es. Arvind Kumar Bhardwaj

Designation: Executive Engineer
HP.PWD B & R

Name & Address of Department/Office: Division Kumarsain