

HIMACHAL PRADESH  
PUBLIC WORKS DEPARTMENT

NO-PW-KMS-WA-Building /2025-

3343-44

Dated:-

28/7/25

To

✓ The Principal ,  
D.A.V.Sr.Sec. Public.School.  
Kumarsain, Tehsil Kumarsain,  
Distt. Shimla (HP).

Subject:-

Request for the issue of Building safety certificate .

Reference: -

Your letter No. 5337 dated 29-07-2025.

In this connection it is intimated that the building safety certificate of D.A.V.Sr.Sec.Public.School building at Kumarsain, Distt. Shimla HP as received from the Assistant Engineer Kumarsain Sub-Division HPPWD Kumarsain vide his letter No. PW-KSD-Building/2025-26-855 dated 27-08-2025 for the year 2025-26 is sent herewith for taking further necessary action.

Encl:- As above.

The Principal,  
D.A.V.Sr.Sec. Public.School,  
Kumarsain, Tehsil Kumarsain,  
Distt. Shimla (HP).

Subject:-

Request for the issue of Building safety certificate .

Executive Engineer,  
Kumarsain Division,  
HPPWD, Kumarsain.

Reference:-

Copy to Assistant Engineer, Kumarsain Sub-Division HPPWD Kumarsain for information with reference to above.

In this connection it is intimated that the building safety certificate of D.A.V.Sr.Sec.Public.School building at Kumarsain, Distt. Shimla HP as received from the Assistant Engineer Kumarsain Sub-Division HPPWD Kumarsain vide his letter No. PW-KSD-Building/2025-26-855 dated 27-08-2025 for the year 2025-26 is sent herewith for taking further necessary action.

Encl - As above.

Executive Engineer,  
Kumarsain Division,  
HPPWD, Kumarsain.

Executive Engineer,  
Kumarsain Division,  
HPPWD, Kumarsain.

Copy to Assistant Engineer, Kumarsain Sub-Division HPPWD Kumarsain for information with reference to above.

Executive Engineer,  
Kumarsain Division,  
HPPWD, Kumarsain.

BUILDING SAFETY CERTIFICATE

No.

Date 28/8/25

It is certified that the existing building D.A.V. Public School Kumarsain (name of the building premises) at Lathi, Kumarsain, distt. Shimla H.P. (address) is having block(s) /Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor(s) in the block	5 (nos.)	-	-	-	-	-

The building is owned/occupied by D.A.V. Public School Kumarsain (name of the institution) have complied with the building safety requirement in accordance with National Building code Rules, and verified by the officers concerned of HP. PWD (Name of Department Govt.) on 25/8/2025 (date of inspection) in the presence of Mr. Ramesh Chand Principal DAV Public School K/sain (name and addresses of the Manager/ Secretary or his representative) and that the building/ premises is fit for occupancy for running school with effect from 25/8/2025 for a period of one years in accordance with rule and subject to compliance of the specific condition as appended.

1. The building has been constructed by the D.A.V Management during 1985 and is a RCC frame structure and cannot be verified structurally but appears safe visually.
2. The structural stability cannot be issued because this building is not constructed by HP. PWD.

Issued on .....at .....by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Assistant Engineer  
Kumarsain Sub-Division  
HPPWD Kumarsain

Signature with seal: Executive Engineer  
Name: Mr. Rakesh Kumar  
Designation: Executive Engineer  
HPPWD BLD  
Name & Address of Department/Office: Kumarsain Division